


FAP, FAR Cores



Type	DIMENSION (unit: mm)		
	A	B	C
FAP2*8*50	2.0+0.1/-0.3	8.0+0/-0.5	50.0±1.2
FAP3*8*40	3.0+0.1/-0.3	8.0+0/-0.5	40.0±1.0
FAP3*8*45	3.0+0.1/-0.3	8.0+0/-0.5	45.0±1.0
FAP3.2*12.2*76.5	3.2+0.1/-0.3	12.2+0/-0.5	76.5±1.5
FAP4*8*45	4.0+0/-0.4	8.0+0/-0.5	45.0±1.0
FAP4*8*50	4.0+0/-0.4	8.0+0/-0.5	50.0±1.0
FAP4.8*13*70	4.8+0/-0.4	13.0+0/-0.6	70.0±1.5
FAP5*15*60	5.0+0/-0.4	15.0+0/-0.6	60.0±1.5

Type	DIMENSION (unit: mm)		
	A	B	C
FAR5*13*55	13.0+0/-0.6	5.0+0/-0.4	55.0±1.2
FAR5*13*80	13.0+0/-0.6	5.0+0/-0.4	80.0±1.6
FAR6*16*60	16.0+0/-0.6	6.0+0/-0.4	60.0±1.4
FAR7*8*50	8.0+0/-0.5	7.2+0.2/-0.5	50.0±1.2
FAR7.2*8*70.5	8.0+0/-0.5	7.2+0.2/-0.5	70.5±1.6
FAR7*8*80	8.0+0/-0.5	7.2+0.2/-0.5	80.0±1.6
FAR9*10*50	10.0+0/-0.6	9.0+0.2/-0.5	50.0±1.2
FAR9*10*60	10.0+0/-0.6	9.0+0.2/-0.5	60.0±1.4
FAR9*10*80	10.0+0/-0.6	9.0+0.2/-0.5	80.0±1.6